

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

FIG. 1




FIG. 2





FIG. 3






FIG. 4

FIG. 5B




FIG. 5A




FIG. 6B

PRIOR ART





FIG. 6A

PRIOR ART



Oil temperature: 40°C
 Delivery pressure: 0.3MPa
 Number of
 rotations: 3000rpm

FIG. 7B





FIG. 7A



Oil temperature: 40°C
Delivery pressure: 0.4MPa
Number of
rotations: 3000rpm

FIG. 8B





FIG. 8A



Oil temperature: 100°C
 Delivery pressure: 0.3MPa
 Number of
 rotations: 3000rpm

FIG. 9B





FIG. 9A



Oil temperature: 100°C
 Delivery pressure: 0.4MPa
 Number of
 rotations: 3000rpm

FIG. 10B




FIG. 10A




FIG. 11

PRIOR ART




FIG. 12




FIG. 13




FIG. 14




FIG. 15B




FIG. 15A




FIG. 16B




FIG. 16A

